

Prepared by:

ATKINS ENGINEERS, INC.

228 ATLANTIC BOULEVARD, SUITE 400 KEY LARGO, FLORIDA 33037-4331

KEYS (305) 451-4556

(305) 451-4557 FAX

MIAMI (305) 444-6260 (305) 442-2201 FAX

www.ae-fl.com

CA # 6964 AR # AA26001691

raig Prandini, A.I.A.

#L # 7929 07/17/2013

JULY 17, 2013

TABLE OF CONTENTS

1.	INTRODUCTION 1
2.	THE PROPERTY1
3.	OCCUPANCY & FIRE RATING2
4.	SITE & LANDSCAPING2
5 .	STRUCTURE3
6.	INTERIOR – GENERAL 6
7.	EXTERIOR6
8.	ROOF 8
9.	HEATING & COOLING SYSTEMS9
10.	ELECTRICAL SYSTEM9
11.	PLUMBING
12.	WINDOWS & DOORS
13.	GENERAL
EXE	HIBITS
REV	/IEWED LISTED DRAWINGS EXHIBIT 1
0	CIVIL DRAWINGS - C12, C13, C13A
0	LANDSCAPING DRAWING – L1
0	ARCHITECTURAL DRAWINGS – A3, A4, A9 THRU A15
0	PLUMBING/MECHANICAL DRAWINGS – P1, M1
0	ELECTRICAL DRAWINGS – E1, E2
SCE	IEMATIC SITE PLANEXHIBIT 2
EXT	TERIOR PHOTOGRAPHS EXHIBIT 3
UNI	TS PHOTOGRAPHS
	UNIT 101A EXHIBIT 4
	UNITS 101B EXHIBIT 5
	UNITS 101C EXHIBIT 6
	UNITS 101D EXHIBIT 7
	UNITS 102A EXHIBIT 8
	······································

TABLE OF CONTENTS

UNITS	102B	EXHIBI'	T 9
UNITS	102C	EXHIBIT	10
UNITS	103A	EXHIBIT	' 11
UNITS	104A	EXHIBIT	12
UNITS	104C	EXHIBIT	' 13
UNITS	105A	EXHIBIT	14
UNITS	105C	EXHIBIT	15
UNITS	107B	EXHIBIT	16
UNITS	108B	EXHIBIT	17
UNITS	108C	EXHIBIT	18
UNITS	111C	EXHIBIT	' 19
UNITS	113A	EXHIBIT	20
UNITS	114C	EXHIBIT	' 21
UNITS	131C	EXHIBIT	22
UNITS	134B	EXHIBIT	23
UNITS	138A	EXHIBIT	24
UNITS	140A	EXHIBIT	25
UNITS	141C	EXHIBIT	' 26
UNITS	145B	EXHIBIT	27
UNITS	146B	EXHIBIT	28
UNITS	148A	EXHIBIT	' 29
UNITS	149C	EXHIBIT	' 30

1. INTRODUCTION

This firm has been retained to provide a condition report of the Peary Court property located at 110 Peary Court, Key West, FL 33040. The condition report is based on a review of the listed drawings in Exhibit 1, the applicable industry standards, a building code that was in effect in Monroe County at the time of construction but was not required for the property and our visual observations of the in place construction at the above referenced community. We believe the findings being presented are representative of the community as of this day. Representatives from Atkins Engineers were on site at the Peary Court site in June and early July 2013.

2. THE PROPERTY

The property consists of 157 two bedrooms, one and one-half bathroom residential townhomes, distributed in 13 four-plexes, 33 tri-plexes and 3 duplexes buildings. A schematic Site Plan indicating townhome relative location is included in Exhibit 2.

The townhomes have similar floor plans. The Ground Floor consists of a living / dining Room, kitchen / breakfast nook and a half bathroom. The second floor consists of two bedrooms, one full bathroom and a utility room. All the townhomes are two stories except for eight units identified as ADA units that are one story. The property's present use is rental apartments.

The structures were built in a period between 1992 and 1994. We have reviewed the Code in effect at this time for Monroe County & Key West and believe that the 1991 Edition of the Standard Building Code would be the appropriate Code for this review. A note on a roof framing plan (A15) indicates the structures were designed for 130mph under the ANSI 58.1 which was the predecessor to the ASCE-7 Wind code that is now a referenced standard to the FBC. If additional information is provided that would change this code to the previous or subsequent editions it is doubtful any meaningful changes would be required. We reviewed the drawings that were provided and compared the requirements of the 1991 Code to the architectural drawings and also to findings during our site visits. We have made observations in 27 of the 157 units on the site and believe, given the consistent findings, that this sampling is representative of the community.

3. OCCUPANCY & FIRE RATING

Occupancy is classified as Residential, Group R-2, Type VI construction and one hour fire rated construction. Section #403.5 of the SBCCI states that for buildings less than 3 stories requires 2 hour rated common walls up to the roof decking, with either non-combustible roof sheathing or fire retardant treatment. FRT plywood could not be identified but we found fire rated drywall demising walls in the attic space that was secure and taped. Insulation was found to be properly place and sealed. A general observation was that the roof attic structure and construction look to be in an "as-new condition"



4. SITE & LANDSCAPING

The driveway and parking areas are asphalt and these areas were in fair condition. The paved areas exhibit signs of wear and some cracking. Recoating is a normal maintenance activity and is required more frequently in south climates. The concrete curbs and sidewalks are in fair condition. Concrete sidewalks exhibit some shrinkage cracks and miscellaneous cracks when in close proximity to large trees.





Landscaping is considered light to medium but consistent with rental communities in the area. Storm water is collected and drains into retention ponds. There are several retention ponds located along Palm Avenue that service this community. Exterior photographs are also included in Exhibit 3.





5. STRUCTURE

The structures are one and two story wood framed buildings. Our review of the construction drawing that were prepared by McCall & Associates Inc. Architect of Montgomery, Alabama indicates that the exterior walls are wood studs 2"x 4"at 16" on center with 1/2" Oriented Strand Board (OSB) exterior sheathing and covered with a layer of vapor barrier sheet stapled to the sheathing. The exterior cladding consist of horizontal vinyl siding. The second floor is framed with 14" deep flat wood trusses. We were able to verify this construction was in general conformance with the drawings.





The foundation was detailed as a concrete slab on grade reinforced with welded wired mesh placed monolithically with a downturn footing. The downturn footing is anchored with 16" diameter piers embedded 3 feet minimum into lime rock. We did not verify the foundation system was as per the drawings. The buildings are performing well and we did not observe settlement or a deficient structural condition. The junction between the concrete slab on grade with the wood studs was observed and photographed at 10 townhomes and were found to be dry and in good working condition with only minor exceptions.





In the attic spaces we observed truss twist straps at all trusses. Rat runs and horizontal bracing was typical and nailed properly. Trusses and roof sheathing are in excellent condition with no signs of moisture or roof leaks. Roof sheathing was firmly attached although we were not able to determine the nail pattern. Shiners or nails that miss trusses that are typically found were not visible in any location.





The roofs shapes consist of hips and gable ends. The gable ends were reinforced by web stiffeners nailed to flat 2x4's in lieu of diagonal bracing. The structures based on our non-destructive observations are performing well and are believed to have been constructed in general accordance with the design drawings prepared by McCall & Associates, Inc. dated 13 April 1992.





The structure of the buildings was in excellent condition with minor signs of moisture or deterioration in some isolated units. We were satisfied with the condition of the wood and particularly the OSB wall sheathing. We have observed the base plate and OSB termination at the floor line from the exterior by prying the vinyl siding up to expose the framing and find it is in good condition with only some exceptions where minor repairs are necessary.





6. INTERIOR – GENERAL

The interior items such as stairs are in code compliance for dimensions and handrails. The stairs are wood framed to the second floor and have 7" risers and 11.5" treads with some variations. One sided handrail is located 35.5" from tread. The stair has a net width of 35".

We did observe some areas where drywall had been removed for maintenance and not replaced properly and that should be addressed.

Floors are finished with vinyl tiles except kitchen floor that are finished in linoleum. Walls are painted drywall with wood baseboard. Kitchen has Whirlpool appliances that include microwave oven, electric range with oven, dishwasher, and refrigerator with top mounted freezer and laminated kitchen countertop with wood doors and melamine lined material. Type X drywall separates units. Type X drywall extends thru attic to underside of roof sheathing. Townhome photographs are included in Exhibits 4 thru 28.

7. EXTERIOR

The exteriors are vinyl wall cladding that is permissible by Code in Type VI construction. Siding in some areas shows signs of aging and areas require repairs, replacement and fastening.





Windows are properly anchored where observed. Windows as indicated by their labeling were AMMA rated at DH-C30 which would translate into a basic wind pressure of 30psf with a minimum structural test pressure of 60psf in accordance with AMMA 101-88. They are not impact. The windows were not required to be impact resistant at the time of construction. Impact glass came in to the industry after Hurricane Andrew and the adoption of ASCE 7 in 1998. The present windows provide the necessary wind load resistance.



Some of the wood post framing that supports carport canopies shows signs of tenant damage, auto collisions, although this was not a typical condition. In some cases this damage has exposed the framing and sheathing and requires repairs. Some of the bottom vinyl siding panels have been damaged by the landscaper's edge trimmer.





8. ROOF

Roof construction for all buildings is metal standing seam roof system with hidden fasteners and a slope of 9 in 12. The ages of the roofs are approximately 20 years old. The roof system is in good condition with minimal observed required repairs. The standing seam metal roof appears to be the original roofing. We did not observe corrosion that would indicate the galvanizing is still providing protection to the metal and that additional useful like remains in the roofing system. The roof panels were installed tight and without waves or loose panels.





Roof attic areas meet code requirements for ventilation. Some vinyl soffits were loose and require fastening. Vinyl vented soffits are clipped to fascia and wall truss tails, a fair amount of vinyl fascia is dislodge or damaged.





9. HEATING & COOLING SYSTEMS

The HVAC is composed of a 2 Ton split system that serves the individual units. The compressor/heat pumps are located outside; Air Handlers with heat strips are located in ground floor closets. The ceiling drywall in the air handler closets should be patched as required, to protect the second floor framing and sealed to the plenum. Heating and air conditioning for each unit appear to be in fair condition and were in working order in the units inspected. Random samplings of the units indicate that some air handlers have been replaced as one would expect given the original construction was 20 years ago.





10. ELECTRICAL SYSTEM

Each unit has a 150 AMP, three wire and single phase service. The Electrical breaker panel is typically located in the utility room at the 2nd floor. Panels were found to have their breakers labeled. A main breaker for each unit is located on the exterior of the building, near the meter.





The electric service is composed of 3-500MCM copper wires. The enclosure is NEMA 3R rated. The grounding wires were found to be #8 wire. NEC requires the grounding to be #1/0 wire and a ground rod and therefore should be remediated.

The heat pumps have a 25 Amp rating and are protected by a 30 Amp breaker. The air handling unit with electric heat is protected by a 60 Amp breaker.

Fire alarm system was composed of hardwired smoke detectors alarms in each bedroom and corridors of the units. GFCI outlets noted at kitchen and bathrooms. Electrical appears to be as original condition with some changes that have been made but in general the units appear to be wired and completed in as indicated by the drawings reviewed.

11. PLUMBING

Ground floor bathroom has a toilet and sink, second floor bathroom has toilet, sink and shower/tub combination. Toilet and sinks have individual disconnect valves. Fixtures appear to be in working order and no immediate major maintenance is anticipated.

Plumbing lines where visible in areas such as the water heater closets and under counter areas were PVC and copper. Plumbing was found to be in good condition.





12. WINDOWS & DOORS


The entrance to the typical unit has a four inch step with a solid door that measures 36" by 80". Sliding glass doors at the rear of the units have a three inch step and measure 72" by 80". The unit windows are single hung, 32" by 66". The windows provide a minimum escape opening of 30" by 28". The bedroom windows meet the egress requirements for sill height and opening size Windows and SGD are not impact resistant or shuttered but the Code at the time of construction did not require such construction. Windows and sliding glass doors were found to be operational and in good condition less normal wear and tear by tenants.


13. GENERAL


As a routine matter in order to avoid any possible misunderstanding, nothing in this report should be considered directly or indirectly as a guarantee for any portion of the structure. This report represents an appraisal of the present condition of the buildings based on our visual non-destructive evaluation of the observed conditions to the extent reasonably possible.


Our review and inspection process is ongoing and this letter outlines our more significant findings with respect to the categories presented. Based on our review the structures were built in general compliance with the original drawings and industry standards that existed at the time of construction in Monroe County.


EXHIBIT 1









































CAPACITY 10,000 NAPS STM.			4	핃	S	픙	PANEL SCHEDULE	쁘				DODDO AMPS STA
PANEL "A", 120/240 VOLT AC, 1-PHASE, 3 WIRE,	VOLT AL	1 1-P	MSE, 3	WIRE		20	AMP, 2	POLE	ML0	99	STR -	150 AMP, 2 POLE M.LO, LOAD CTR - FLUSH MOUNTED
Cough Doughlon	LKT. BKR.	BKR.	JA/PHASE	HASE	8	CKT	VA/PHASE	WSE	DKT, BKS	1966	1	
Edolpachi Served	180	HOLL	4	9	Q.	No.	×	33	POLE	至		EQUIPMENT SERVED
RANGE RECEPTACLE	6	2.0	0009		-	74	4010		*2	20	FIDE	FIR HEAT PLIMP
		•		6000	2	*		4010				
DENTA RECEPTACE	30	. 7	1. 2500		w	2	4000		4.2	13	TER AHU	OHO.
		•		2200	2	100		4000				
FIR MAILY HEATER	S	2.0	2 • 2250		6	9	1500		4	8	DISHA	DISTANDAMES RECEPTACLE
		•		TOTAL	=	::		1550	-	02	DISPO	ISPOSAL PEDDIAGLE
REFROEWEDR RECEPTACLE	22	-	1300		2	2	1500		-	20	WAS !!	ASHER MECENTALL
KITCHEN COUNTER NECEPTAGE	70	-		1500	2	5		1550	-	20	RECEPT	AT SECHOOM & BREAKLAST
KITCHEN COUNTEN RECEPTACLE	20	-	1590		=	10	1500		-	20	RECEPT	T BEDROOM & BPEAGAST
KITCHEN COUNTER RECEPTACE	20	¥n		1500	22	07		1500	-	07	HEGE	RECEPT LIVING & DIMMERS IN
LIGHTS LYING, DINNING, & BDRW	30	-	1502		21	22	1500		-	25	US K	IS KTOHEN, BREAKTAST, & BORN
SPACE DRLY		-			23	24					SPACE	PACE CNLY
SPACE DACY					52	97					SPACE	SPACE CALLY
STACE DALY					27	28			-		SPACE	OND
SPACE UNLY					P	35			-		SPACE	SPACE CALLY

LOCKABLE THE CHOUT BREADS
 GROUND FAUL CAPACITY NUDSHIFTS THE

TOTAL COMMECTED VOLT — AMPS 29260 | 25260 = 53520 VA

BREAKER INTERRUPTING CAPACITY 10,330 AMPS SYN			A A	Ä	ဟ	끙	PANEL SCHEDULE			BRACED FOR MINIMUM 10,000 AMPS SYM
PANEL "6", 126/240 VOLT AC, 1-PIMSE, 3 WIRE,	VOLT A	C, 1-PI	MSE. 3	WIRC,		98	AMP. 2 POL	C MLO	LOACO	150 AMP, 2 POLE M.L.O. LOADCENTER - JUUSH MOUNTED
A Part of the Part	CMT	CMT. BASK	N.	11	CIG. ONT	CKT	VA/PHASE	25	BKH	
EGOIPMENI SERVED	TRP	POLE	~	21	No	No	4	PO(5	TRIP	EGUIPMENT SERVED
RANDE RECEPTABLE	÷	17	2009			17	2460		175	FOR HEAT PLINT
		•		9200	-	+	2400			
DRYER RECEPTACLE	20	7	2500		Lis.	9	5500		99	UNA HCI
		•	g	1300	1	-	Spile			
FOH WATER HEATER	20	14	2250		0	9	1500	-	50	DISHMASHLY PECEPTAGE
		•		6527		12	1500	-	377	DISPOSAL PEGETIAGE
REPROSNATOR RECEPTABLE	10	+	1500		77	*	1500	-	52	WASHER RECEPTABLE
KITCHEN COUNTER RECEPTACLE	01	+		1500	ur.	40	1300	-	25	RECEPT, CHINING & BREAKFAST
KITCHEN COUNTER RECEPTACLE	30	0.0	1300		1	0	1550	-	25	WELLEY LINNS HOOM
KITCHEN COUNTER RECEPTACLE	20	+		1500	-	20	1500		20	RECEPT BEDROOM & BATHHUGM
LIGHTS 15T FLOOR	D‡	+	1500		21	7	b	-	20	LIGHTS 2ND FLOOR
HECEPT, BETWEEN	R			200	14	75	ı		13	THE SHE
SPACE UNLY	107	-			52	E		-	50	SPACE UNCO
SPACE ONLY	20	-			27	2.8	i	-	20	SPACE ONLY
SPACE DALY	20	-			000	2		-	20	SPACE DALY

LOCKABLE TYPE CIRCUIT BREAKER
 CHOUND FAULT CAPACITY INTERUPTER

TOTAL CONNECTED VOLT - AMPS [23150 27650] = 56800 VA

	LIGHT	2	FIXTU	LIGHTING FIXTURE SCHEDULE	EDULE
MARK	MANUFACTURER & CATALOG No.	Ş.	SAM	DNILLING	DESCRIPTION
~	SEAGULL 7932-68 WHITE	-	PL13	SURFACE	SURFACE 10" ROUND GLORE
100	State of the state of	-	V	PENDANT	118 CONTENTS TO 18 18 18 18 18 18 18 18 18 18 18 18 18
J	APSCO 200-240 WHITE	7	F40WW	SURFACE	4" PLUORESCENT WRAP AROUND
15	EAGLE 4800-PL7	-	17	WAL BRICE	WATE LEXAN GLOBE
Dec	BROAN SDL-62	9	WWOZE	WALL ABOVE	COMPINATION MEDICINE CARNET/1, CHILD
w	APSC0 905-PL13-PC	se	FL'3.	CA TAN	WITH PHOTO CELL

GENERAL NOTES:

TAI 280 GC STECRISSU TO THE EST OF BUREATON


- I PROVIDE NOT NATIOL WITTER CONTROL ON SUBRINGE OF MAINT-HANT STRUCTURE. PROVIDE 4 GAV., 1 NOW WITH CHIRDRY AS DEFORMED CLUM, NOT 50 More COMMUNISALING NATIONAL SHOWN BROKEN STRANGE COLUMNE, UNIT TAKE. TREATE CLUMNED THE WASTER TO STRANGE OF WASTER THE THE COLUMNED THE WASTER THE WASTE
- 2: PROVOC NO MEN'LA A 2" COMBAIL WITH TAIL STRIKE THOU TAGS FEDICIAL, STLEE FIT OT THE STRIKE THE STRIKE THE STRIKE THE STRIKE THE WARRINGS AND WELL THE WARRINGS AND WELL AND THE STRIKE AND WELL AND THE STRIKE THE STRIKE
 - 3. PROVIDE AND NETALL 1" NO POR SITE PLAN ODERNA NOT AS SHEEL C-15. TO COLDENORM SEALED STATE OF SHEEL CONTROLLER TO BE SHEEL SHEEL
 - (4 COORDINATE TELEPHONE/CABLE TV WITH LOCAL AUTHORITIES
- S SEE SITE DEVELOPEMENT RECLIREMENTS FOR INFORMATION PERTAINING TO SERVICE FROM SITE PEDESTALS TO MULTI-UNIT STRUCTURES
- S. ALL WORK & WRING SHAJJ WEET OR EXCEED ALL NATIONAL ELECTRICAL CODE AND ALL IOCAL CODE REQUIREMENTS

CONSTRUCTION OF SO FAMALY HOUSEN! CURTS
AT PERRY COURT, NAVAL ARE STATION,
TRUMBO POINT ANNINA, KEY WIEST, FLORIDA
ELECTROCAL INSES AND PAIRL SCHENLES

- REQUIREMENTS
- A ALL MICE SWALE BE ROMEN THRE UNLESS MOTTO COPPER COMBLETOR. INSTALL IN CONDUIT OR PICTAL SINGLINED BY CODICS.

 A ALTOMINED BY CODICS.

 FALL MICH THAN INVALVABLE MECHANICAL COMPANY & PIERS LICKTICALS SPALL BE COMPINED BETWEEN



ELECTRIC, TELEPHONE, CABLE T.V. SERVICE ENTRANCE DETAIL NO SOUT

EXHIBIT 2




EXHIBIT 3

PEARY COURTS



SITE-001



SITE-002



SITE-003



SITE-004



SITE-005



SITE-006



SITE-007



SITE-008



SITE-009



SITE-010



SITE-011



SITE-012



SITE-013



SITE-014



SITE-015



SITE-016



SITE-017



SITE-018

KEY WEST



SITE-019



SITE-020





SITE-022



SITE-023



SITE-024



SITE-025



SITE-026



SITE-027



SITE-028



SITE-029



SITE-030



SITE-031



SITE-032



SITE-033



SITE-034



SITE-035



SITE-036



SITE-037



SITE-038



SITE-039



SITE-040



SITE-041



SITE-042



SITE-043



SITE-044



SITE-045



SITE-046



SITE-047



SITE-048





SITE-049 SITE-050

EXHIBIT 4



101A-001



101A-002



101A-003



101A-004



101A-005



101A-006



101A-007

EXHIBIT 5



101B-001



101B-002



101B-003



101B-004



101B-005



101B-006

EXHIBIT 6



101C-001



101C-002



101C-003



101C-004



101C-005



101C-006



101C-007



101C-008



101C-009



101C-010



101C-011



101C-012

KEY WEST



101C-013



101C-014



101C-015



101C-016



101C-017



101C-018

KEY WEST



101C-019



101C-020



101C-021



101C-022



101C-023



101C-024

KEY WEST



101C-025



101C-026



101C-027



101C-028



101C-029



101C-030



101C-031



101C-032



101C-033



101C-034



101C-035



101C-036

KEY WEST



101C-037



101C-IR-001




101C-IR-002



101C-IR-003



101C-IR-004



101C-IR-005

KEY WEST

EXHIBIT 7



101D-001



101D-002



101D-003



101D-004



101D-005



101D-006



101D-007



101D-008



101D-009



101D-010



101D-011



101D-012

KEY WEST



101D-013



101D-014



101D-015



101D-016



101D-017



101D-018

KEY WEST







101D-020



101D-021



101D-022



101D-023



101D-024



101D-025



101D-026



101D-027



101D-028



101D-029



101D-030

KEY WEST



101D-031



101D-032



101D-033



101D-034



101D-035



101D-036







101D-038



101D-039



101D-040



101D-041



101D-042

KEY WEST



101D-043



101D-044



101D-045



101D-046



101D-047



101D-048



101D-049



101D-050



101D-051



101D-052



101D-053



101D-054

KEY WEST






101D-055 101D-056




101D-057



101D-IR-001



101D-IR-002



101D-IR-003



101D-IR-004



101D-IR-005



101D-IR-006

KEY WEST

EXHIBIT 8



102A-001



102A-002



102A-003



102A-004



102A-005



102A-006



102A-007



102A-008



102A-009



102A-010



102A-011



102A-012



102A-013



102A-014



102A-015



102A-016



102A-017



102A-018

KEY WEST



102A-019



102A-020



102A-021



102A-022



102A-023



102A-024







102A-026



102A-027

EXHIBIT 9




102B-001



102B-002



102B-003



102B-004




102B-005



102B-006

KEY WEST





102B-007 102B-008


EXHIBIT 10




102C-001



102C-002



102C-003



102C-004



102C-005



102C-006







102C-008



102C-009



102C-010



102C-011



102C-012

KEY WEST







102C-014



102C-015



102C-016

EXHIBIT 11



103A-001



103A-002



103A-003



103A-004



103A-005



103A-006



103A-007



103A-008



103A-009



103A-010



103A-011



103A-012



103A-013



103A-014



103A-015



103A-016



103A-017



103A-018

KEY WEST



103A-019



103A-020



103A-021



103A-022



103A-023



103A-024



103A-025



103A-026



103A-027



103A-028



103A-029

EXHIBIT 12



104A-001



104A-002



104A-003



104A-004



104A-005



104A-006

KEY WEST



104A-007



104A-008



104A-009



104A-010



104A-011



104A-012

KEY WEST



104A-013



104A-014



104A-015



104A-016



104A-017



104A-018

KEY WEST



104A-019



104A-020



104A-021



104A-022



104A-023




104A-024

KEY WEST



104A-025



104A-026



104A-027



104A-028



104A-029



104A-030








104A-032



104A-033



104A-034



104A-IR-001




104A-IR-002



104A-IR-003



104A-IR-004



104A-IR-005

KEY WEST

EXHIBIT 13




104C-001



104C-002




104C-003



104C-004



104C-005



104C-006



104C-007



104C-008



104C-009



104C-010



104C-011



104C-012

EXHIBIT 14



105A-001



105A-002



105A-003



105A-004



105A-005



105A-006

KEY WEST



105A-007



105A-008



105A-009



105A-010



105A-011



105A-012



105A-013



105A-014



105A-015



105A-016



105A-017




105A-018

KEY WEST



105A-019




105A-020



105A-021



105A-022



105A-023



105A-024



105A-025



105A-026



105A-027



105A-028



105A-029



105A-030

KEY WEST



105A-IR-001



105A-IR-002



105A-IR-003



105A-IR-004



105A-IR-005



105A-IR-006


KEY WEST




105A-IR-007



105A-IR-008



105A-IR-009



105A-IR-010



105A-IR-011

KEY WEST







105C-002



105C-003



105C-004



105C-005



105C-006

KEY WEST



105C-007



105C-008



105C-009



105C-010



105C-011



105C-012

KEY WEST



105C-013



105C-014



105C-015



105C-016



105C-017



105C-018







105C-020



105C-021



105C-022



107B-001



107B-002



107B-003



107B-004



107B-005



107B-006

KEY WEST



107B-007



107B-008



107B-009



107B-010



107B-011



107B-012





107B-013

107B-014





107B-015

107B-016





107B-017

107B-018

KEY WEST





107B-019

107B-020



107B-021





108B-001

108B-002



108B-003



108C-001



111C-001



111C-002



111C-003



111C-004



111C-005



111C-006



113A-001




113A-002



113A-003



113A-004



113A-005



113A-006

KEY WEST





113A-007 113A-008





114C-001





114C-003





131C-001 131C-002



134B-001



134B-002



134B-003



134B-004



134B-005



134B-006



134B-007




134B-008



134B-009



134B-010



134B-011



134B-012

KEY WEST







134B-014



134B-015



134B-016



134B-017



134B-018

KEY WEST



134B-019



134B-020



134B-021



134B-022



134B-023



134B-024

KEY WEST



134B-025



134B-026



134B-027



134B-028




134B-029



134B-030





134B-031 134B-032





134B-033 134B-034



134B-IR-001



134B-IR-002




134B-IR-003



134B-IR-004



134B-IR-005



134B-IR-006

KEY WEST



138A-001



138A-002



138A-003



138A-004



138A-005



138A-006



138A-007



138A-008



138A-009



138A-010



138A-011



138A-012



138A-013



138A-014



138A-015



138A-016



138A-017



138A-018

KEY WEST



138A-019



138A-020



138A-021



138A-022



138A-023



138A-024







138A-026



138A-027



138A-028







138A-030

KEY WEST



138A-031



138A-032



138A-033



138A-034



138A-035



138A-036



138A-037



138A-038



138A-039



138A-040



138A-041




138A-042

KEY WEST



138A-043



138A-044



138A-045



138A-046



138A-047



138A-048

KEY WEST



138A-049



138A-050



138A-051



138A-052



138A-053




138A-054



138A-IR-001



138A-IR-002



138A-IR-003



138A-IR-004



138A-IR-005



138A-IR-006

KEY WEST



138A-IR-007



138A-IR-008



138A-IR-009



138A-IR-010

EXHIBIT 25



140A-001



140A-002



140A-003



140A-004



140A-005



140A-006

KEY WEST



140A-007



140A-008



140A-009



140A-010



140A-011



140A-012



140A-013



140A-014



140A-015



140A-016



140A-017




140A-018

KEY WEST



140A-019



140A-020



140A-021



140A-022



140A-023



140A-024



140A-025



140A-026



140A-027



140A-028



140A-029



140A-030

KEY WEST

EXHIBIT 26







141C-002



141C-003



141C-004



141C-005



141C-006





141C-007

141C-008



141C-009

EXHIBIT 27



145B-001



145B-002



145B-003



145B-004



145B-005



145B-006

KEY WEST



145B-007



145B-008



145B-009



145B-010




145B-011



145B-012

KEY WEST



145B-013



145B-014



145B-015




145B-016



145B-017




145B-018



145B-IR-123

145B-IR-124



145B-IR-125

EXHIBIT 28





145B-019 145B-020



146B-001



146B-002



146B-003



146B-004



146B-005



146B-006

KEY WEST



146B-007



146B-008



146B-009



146B-010



146B-011



146B-012



146B-013



146B-014



146B-015




146B-016



146B-017



146B-018





146B-020







146B-022








146B-024

KEY WEST



146B-025



146B-026



146B-027



146B-028




146B-029



146B-030



146B-031



146B-032



146B-033



146B-034



146B-035



146B-036

KEY WEST



146B-037



146B-038



146B-039




146B-040



146B-IR-001



146B-IR-002



146B-IR-003



146B-IR-004



146B-IR-005



146B-IR-006

KEY WEST

EXHIBIT 29



148A-001




148A-002



148A-003



148A-004



148A-005



148A-006

KEY WEST





148A-007









148A-010







148A-012



148A-013



148A-014



148A-015



148A-016



148A-017



148A-018

KEY WEST



148A-019



148A-020



148A-021



148A-022



148A-023



148A-024





148A-025 148A-026





WSHOCAL C

148A-029 148A-030 KEY WEST



148A-031



148A-032



148A-033



148A-034




148A-035



148A-036

KEY WEST



148A-IR-001




148A-IR-002



148A-IR-003



148A-IR-004



148A-IR-005



148A-IR-006

KEY WEST

EXHIBIT 30







149C-002



149C-003



149C-004



149C-005



149C-006

KEY WEST



149C-007



149C-008



149C-009



149C-010



149C-011



149C-012



149C-013



149C-014



149C-015



149C-016



149C-017



149C-018


KEY WEST





149C-019 149C-020





149C-021 149C-022



149C-IR-001